

# Klay Instruments B.V.

### Nijverheidsweg 5, PO Box 13, NL 7991 CZ Dwingeloo, Netherlands

is hereby authorized to continue to apply the 3-A Symbol to the models of equipment, conforming to 3-A Sanitary Standards for:

## Number 74-07 74-07 (Sensors and Sensor Fittings and Connections)

#### set forth below

```
CIP Models: Pressure and Level Transmitters:
9000-SAN-A to H-W(85)-G150-G153, Weld-on nipple;
9000-SAN-A to H-L(1.5", 2" or 3")-G153, Tri Clamp;
9000-SAN-A to H-X4-G153, Varivent baseplate from GEA;
9000-SAN-A to H-X7-G153, DRD flange;
8000-SAN-B to I-W(85)-G150-G153, Weld-on nipple;
8000-SAN-B to I-L(1.5", 2" or 3")-G153, Tri Clamp;
8000-SAN-B to I-X4-G153, Varivent baseplate from GEA;
8000-SAN-B to I-X7-G153, DRD flange;
4000-SAN-1 to 5-W(85)-G150-G153, Weld-on nipple;
4000-SAN-1 to 5-L(1.5", 2" or 3")-G153, Tri Clamp;
4000-SAN-1 to 5-X4-G153, Varivent baseplate from GEA;
4000-SAN-1 to 5-X7-G153, DRD flange:
2000-SAN-1 to 5-W(85)-G150-G153, Weld-on nipple;
2000-SAN-1 to 5-L(1.5", 2" or 3")-G153, Tri Clamp;
2000-SAN-1 to 5-X4-G153, Varivent baseplate from GEA:
2000-SAN-1 to 5-X7-G153, DRD flange;
Hydrobar-I-Cable(xx)-1 to 3-L(1.5", 2" or 3")-G10-G153;
Hydrobar-I-Cable(xx)-B to H-L(1.5", 2" or 3")-G10-G153;
Hydrobar-I-Cable(xx)-FR-L(1.5", 2" or 3")-G10-G153;
Hydrobar-Cable(xx)-FR-L(1.5", 2" or 3")-G10-G153.
```

# Temperature Transmitters:

TT-E-D-X4-L..xD..S-G153, -200..+400 °C, Varivent baseplate from GEA; TT-E-D-L(1.5" or 2")-L..xD..S-G153, -200..+400 °C, Tri Clamp.

#### Level Switches:

VSS-L(1.5" or 2")-100-3-G153, PNP output, Tri Clamp.

### VALID THROUGH: December 31, 2025

The issuance of this authorization for the use of the 3-A Symbol is based upon the voluntary certification, by the applicant for it, that the equipment listed above complies fully with the 3-A Sanitary Standard(s) designated. Legal responsibility for compliance is solely that of the holder of this Certificate of Authorization, and 3-A Sanitary Standards, Inc. does not warrant that the holder of an authorization at all times complies with the provisions of the said 3-A Sanitary Standards. This in no way affects the responsibility of 3-A Sanitary Standards, Inc. to take appropriate action in such cases in which evidence of nonconformance has been established.

NEXT TPV INSPECTION/REPORT DUE: January 2026